

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**


## **Agenda**

---

**Subject** Rough Review Agenda  
**Project** « Diaper Genie » Playtex  
**Date** 2/8/01

---

- 1. Review 2D layouts of:**
  - 1.1. Latching systems
  - 1.2. Foot pedal systems
  
- 2. Review schematic sketches**
  - 2.1. Top opening (Pros and cons)**
    - 2.1.1. Cartridge loading option 1
    - 2.1.2. Cartridge loading option 2
  - 2.2. Side door opening (Pros and cons)**
    - 2.2.1. Cartridge loading sequence
  - 2.3. Integral bucket (Pros and cons)**
    - 2.3.1. Cartridge loading sequence
  - 2.4. Foot pedal**
    - 2.4.1. Option 1
    - 2.4.2. Option 2
  - 2.5. Motorized schematics**
  - 2.6. Cutting methods (Pros and cons)**
    - 2.6.1. Retractable cutter
    - 2.6.2. Remote cutter
    - 2.6.3. Auto-cutter, mockup and discussions.



## **Pros:**

- More stable than side door (emptying)
- Better ergonomics
- Less squatting
- Easy disposal
- Easy reload (*anywhere you want*)
- Easy to seal (*simple cross section*)
- Cost reduction (*less part count*)

## **Cons**


- Cartridge load might be cumbersome
- Odor control and cleaning (*no internal bucket*)
- Odor Blast
- Hygiene perception
- Limited cutter options

## **Top Opening**

2.1

PLAYTEX Products, Inc.  
Next Generation Genie - 61601  
© Bresslergroup 2001

BRESSLERgroup  
Philadelphia, PA USA  
215.561.5100




## Cartridge loading

2.2.1

PLAYTEX Products, Inc.  
Next Generation Genie - 61601  
© Bresslergroup 2001

BRESSLERgroup  
Philadelphia, PA USA  
215.561.5100



## **Pros:**

- Easy disposal
- Easy cartridge load
- Easy access to the inside (*cleaning*)
- Any of selected cutting method is doable
- Less part count.

## **Cons**


- Difficult to seal (*complex and extended surfaces*)
- Odor control?
- Stability?

### ***Integral bucket***

2.3

PLAYTEX Products, Inc.  
Next Generation Genie - 61601  
© Bresslergroup 2001

BRESSLER group  
Philadelphia, PA USA  
215.561.5100



2.3.1

## *Cartridge loading*

*PLAYTEX Products, Inc.*  
*Next Generation Genie - 61601*  
© Bresslergroup 2001

**BRESSLERgroup**  
Philadelphia, PA USA  
215.561.5100

## ***Motorized schematics***

**PLAYTEX Products, Inc.**  
**Next Generation Genie - 61601**  
© Bresslergroup 2001

**2.5**

